Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 8/13/2013, 8/15/2013	Man Days: 4
Inspection Unit: Marion	
Location of Audit: Marion	
Exit Meeting Contact: Dallas Jett	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Kevin Hecker, Matt Smith	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

CONSTRUCTION INFORMATION			
Location of Construction:	Construction Performed By:		
organ Avenue and Atchison Street. K&S Construction		K&S Construction (contracted by Ameren Illinois)	
Contractor Foreman:	Rick Briener		
Operator Inspector:	Bill Moser		
Person(s) On Job Site			
James Brust			

Description of Construction:

K&S Construction (contracted by Ameren Illinois) completed a tie in between 2 newly installed steel mains at the intersection of Morgan Avenue and N. Atchison Street in Marion, Illinois.

MAIN INSTALLATION		Status
[192.55]	Steel	Yes
[192.59]	PE	No
[192.59]	Other	No
[192.5]	Class location :	Class 3
[192.619,192.621,192.623]	MAOP	60 psig
[192.63]	Pipe Size :	6.625"
[192.55,192.59]	Specification :	API 5L-0292

AMEREN ILLINOIS COMPANY/8-15-2013

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Manufacturer :	Romble Co.
[192.55,192.59]	Pipe Grade :	X42/X52
[192.55,192.59]	Wall Thickness :	.219"
[192.63(a)(2)]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
[192.227]	Date of Welder qualification:	6/10/2013
[192.227]	Welder's Name:	James Brust
[192.225,192.275,192.277,192.27	9,192.283] Is pipe joined in accordance with approved written procedures?	Not Applicable
General Comment: The main tie-in observed was between 2 s	teel lines. No plastic was used during this audit.	
[192.285]	Date of Plastic Joining Qualification :	Not Applicable
General Comment: The main tie-in observed was between 2 s	teel lines. No plastic was used during this audit.	
[192.285]	Joiner's name:	Not Applicable
General Comment: The main tie-in observed was between 2 s	teel lines. No plastic was used during this audit.	
[192.455]	Is buried metallic pipe coated?	Satisfactory
General Comment: 15-17 mil/rock guard coating.		
[192.461]	Does coating meet 192.461?	Satisfactory
[192.455(a)(1)]	Is cathodic protection being provided?	Satisfactory
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
[192.455(a)(1)])] Is cathodic protection being provided? By Rectifier:	
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	
92.467] Are pipelines electrically isolated from other underground metallic structures?		Satisfactory
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable
General Comment:		
There are no above ground facilities at this	location.	
[192.303]	Are comprehensive written construction specifications available and adhered to?	Satisfactory
General Comment:		
Copies of construction procedures are kep	4 in the twick	

AMEREN ILLINOIS COMPANY/8-15-2013

Page 2 of 5

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.305]	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
General Comment:	·	
Foreman for K&S and an inspector from Ame	eren Illinois were on site.	
[192.307]	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability? Satisfactory	
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Not Applicable
General Comment:		
No plastic pipe was used during this audit.		
[192.321(e)]	Does plastic pipe have means of locating while underground?	Not Applicable
General Comment:		
No plastic pipe was used during this audit.		
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
[192.327]	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory
General Comment:	· · · · · · · · · · · · · · · · · · ·	
Pipe was bored in deeper than required dept	h. East/West run was approximately 62" deep, the North/South run was approximately 72" d	leep.
[192.503]	Are general testing requirements being met?	Satisfactory
General Comment:		
Pressure tested at 100 psi. Test medium wa	s air.	
[192.517]	Are records being made of strength and leak tests?	Satisfactory
92.807] Were covered employees Operator Qualification records reviewed to ensure qualification?		Satisfactory
[192.805(c)]	Were non-qualified personnel being "directed and observed" by a qualified individual?	
General Comment:		
There were no non-qualified employees on the	nis jobsite.	
[192.805(c)]	Were span of control limitations being followed?	Satisfactory
General Comment:		
All workers performing covered tasks at the s	site were qualified to do so.	
Was a Protocol 9 (Form 15) Comple	eted?	No

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.614]	Were One Call Notifications performed as	required? Satisfactory
General Comment:	·	·
All JULIE tickets required for this proje	ect were refreshed on 8/12/13, effective 8 a.m.	
[192.614] Dig Ticket #		A2192946
General Comment:	•	·
All JULIE tickets associated with the p	roject:	
A1991846		
A1991830		
A1991779		
A1991765 A2192946		
A2192946 A1991789		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.